



National Oil Spill Detection and Response Agency

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed by all participating parties in the field

Site Organization		Mandatory Information Required	
Company Name		UERL	
Incident Number		UERL/HSE/01/24	
Type of Complaint/Incident		☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution ☐ Others (specify).....	
Incident Details			
Date of Incident		16/02/2024	
Date first reported		17/02/2024	
Date of first investigation		DD/19/02/2024	
Date of follow-up investigation		DD:MM:YYYY	
Time of investigation		24hrs	
Estimated quantity spilled		BARRIS. 075661	
Site Details			
Facility Address		KP5 Pipeline ROW	
Position of Spill/Leak			
Location		GPS Coordinate	N 04° 32' 47.95" E 08° 11' 51.84" W
OML:			
Spill Area		☐ Land ☒ Swamp ☐ Fresh Water ☐ Mangrove ☐ Coastline ☐ Nearshore ☐ Offshore ☐ Others observations around the spill point (specify)..... Seasonal Swamp.....	
Structural Controls in Place		☒ Boom ☐ Trenches ☐ Bund wall ☒ Sorbents ☐ Others (specify).....	
Circumstances Around Spill point			
Visual Observation of Hole Point		☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☒ 3 O' Clock ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock	
Type of Contaminant		☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products ☐ Others (specify).....	
Facility		☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig ☐ Storage tank ☐ Compressor Plant ☐ Others (specify).....	

Additional Description of
Spill Point

- | | |
|--|---|
| ☐ Hacksaw Marks | ☐ Drilled Holes |
| ☐ Hacksaw cut | ☐ Blast |
| ☐ Theft (illegal bunkering) | ☐ Flare System/Bund wall failure |
| ☐ Valve failure | ☐ Saver pit overflow |
| ☐ Missing Pipeline/Flowline | ☐ Third party tampering with valve setting |
| ☐ Failed Clamp | ☐ Third party tampering with flange |
| ☐ Well head tampering | ☐ Inward dent |
| ☒ Failed clamp | ☐ Surge vessel overflow |
| ☐ Bulging outward | ☐ Relief valve failure |
| ☐ Complete rupture | ☐ Others (specify)..... |

Seal Leakage

Graphic Description of Leak Point (sketches/illustrations)

1. Hacksaw cut

2. Failed clamp

3. Failed clamp

4. Failed clamp

5. Failed clamp

6. Failed clamp

Impact of Incident	
Properties impacted by incident	☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water ☐ Venerable Objects ☐ Others (specify)..... <u>N/A</u>
Nature of impact	☐ Oil stained vegetation ☐ Oil stained fishing net ☐ Dead floating fishes ☐ Dead floating Crabs ☐ Withering of vegetation ☐ Others (specify)..... <u>N/A</u>
Distance from the nearest Receptors potentially at risk	☐ Farmlands [,m] ☐ Build-up area [,m] ☐ Fish Farm/Pond [,m] ☐ Drinking water source [,m] ☐ Farms ☐ Fishing [,m] ☐ Reserved and protected area [,m]
Delineation of impacted area	☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

Extend of Impact					
S/N	Northing	Easting	S/N	Northing	Easting
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS

a) Community (indicate name)	b) Land (indicate area in m²)
i. <u>Hakdim Ukpa</u>	i. <u>6.25sq.m</u>
ii.	ii.
iii.	iii.
iv.	iv.

Creeks/Creek lets			
☐ Tidal		☐ Non Tidal	
NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Swamp			
☐ Tidal		☐ Non Tidal	
NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Shoreline/water			
☐ Tidal		☐ Non Tidal	
NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Photograph/Map/Chart Ref.	☒ Still Photograph ☒ Video coverage ☐ Mapping
Samples taken	N/A
Investigation	☒ Foot ☐ Boat ☐ Aircraft ☐ Drone

REMARKS/RECOMMENDATION

Replace failed clamp and improve
submarine surveillance

DATE/TIME INVESTIGATION ENDED 14/02/2024 14:00

Name and Signature of Participants					
NOSDRA			Local Government Council		
S/N	Name	Signature	S/N	Name	Signature
1.	Odungido, A. E.		1.	Brown Daniel Afia	
2.	Engr. Grafton Obediah		2.		
3.	GRACE BERKHAMIN		3.		
Company			Company		
1.	Aladei, E. Pius		1.	IBORO AKPAN	
2.			2.	Rohini Akimbubaye	
3.			3.		
State Ministry of Environment			Community		
1.	Engr. Aniete Emah		1.	Prince Adekunle	
2.			2.	Dr. David Ayegbade	
3.			3.	Kate E. Ope	