



National Oil Spill Detection and Response Agency

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed by all participating parties in the field

Site Organization		Mandatory Information Required	
Company Name		FUN Manifold	
Incident Number			
Type of Complaint/Incident		☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution ☐ Others (specify).....	
Incident Details			
Date of Incident		04/08/2023	
Date first reported		04/08/2023	
Date of first investigation		03/08/2023	
Date of follow-up investigation		05/06/2024	
Time of investigation		14:53	
Estimated quantity spilled			
Site Details			
Facility Address		FUN manifold, Mkpatak, Ibeno	
Position of Spill/Leak			
Location		GPS Coordinate	N 4° 33' 37.67" E 8° 0' 24.75"
OML:			
Spill Area		☒ Land ☐ Swamp ☐ Fresh Water ☐ Mangrove ☐ Coastline ☐ Nearshore ☐ Offshore ☐ Others observations around the spill point (specify).....	
Structural Controls in Place		☒ Boom ☒ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....	
Circumstances Around Spill point			
Visual Observation of Hole Point		☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock	
Type of Contaminant		☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products ☐ Others (specify).....	
Facility		☐ Pipeline ☒ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)..... ROW	
Cause of spill		Company	Third Party Interference
		☐ Corrosion ☐ Equipment Failure ☐ Operational/Maintenance Error ☐ Bund wall overflow	☐ Vandalization ☐ Oil Theft ☐ Illegal Refining ☒ Others Failed open drain lining wall
			Others ☐ Accident ☐ Mystery

Additional Description of Spill Point

- ☐ Hacksaw Marks
- ☐ Hacksaw cut
- ☐ Theft (illegal bunkering)
- ☐ Valve failure
- ☐ Missing Pipeline/Flowline
- ☐ Failed Clamp
- ☐ Well head tampering
- ☐ Failed clamp
- ☐ Bulging outward
- ☐ Complete rupture

- ☐ Drilled Holes
- ☐ Blast
- ☐ Flare System/Bund wall failure
- ☐ Saver pit overflow
- ☐ Third party tampering with valve setting
- ☐ Third party tampering with flange
- ☐ Inward dent
- ☐ Surge vessel overflow
- ☐ Relief valve failure
- ☐ Others (specify).....

Graphic Description of Leak Point (sketches/illustrations)

Impact of Incident

Properties impacted by incident		☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water ☐ Venerable Objects ☐ Others (specify).....	
Nature of impact		☒ Oil stained vegetation ☐ Oil stained fishing net ☐ Dead floating fishes ☐ Dead floating Crabs ☐ Withering of vegetation ☐ Others (specify).....	
Distance from the nearest Receptors potentially at risk		☐ Farmlands [,m] ☐ Build-up area [,m] ☐ Fish Farm/Pond [,m] ☐ Drinking water source [,m] ☐ Farms ☐ Fishing [,m] ☐ Reserved and protected area [120m]	
Delineation of impacted area		☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW	

Extend of Impact

[illegible]

a) Community (indicate name)	b) Land (indicate area in m ²)
i. <u>Nit</u>	i.
ii.	ii.
iii.	iii.
iv.	iv.

Creeks/Creek lets

☐ Tidal		☐ Non Tidal	
NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Swamp

☐ Tidal		☐ Non Tidal	
NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

River

River			
☐ Tidal		☐ Non Tidal	
NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Shoreline/water

☐ Tidal☐ Non Tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Photograph/Map/Chart Ref.	☐ Still Photograph	☐ Video coverage	☐ Mapping
Samples taken			
Investigation	☐ Foot	☐ Boat	☐ Aircraft ☐ Drone

REMARKS/RECOMMENDATION

.....

.....

.....

.....

.....

DATE/TIME INVESTIGATION ENDED

05/06/2024 14:43

Name and Signature of Participants					
NOSDRA			Local Government Council		
S/N	Name	Signature	S/N	Name	Signature
1.	ENGIR MERVIS ODORO		1.		
2.	Odungide, A. C		2.		
3.	Okobah, O GAXTON		3.		
DPR			Company		
1.			1.	Emmanuel Iye	
2.			2.	Shadrach Ogburne	
3.			3.	Justice Christopher	
State Ministry of Environment			Community		
1.			1.	Daniel Etim	
2.			2.		
3.			3.		