

2024/LNO/MLI/054



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: INDORAMA - ELEME PETROLEUM COMPANY

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) NON-GAS LEAK INCIDENT

3. Incident Details

- i. Date of Incident: 11-05-2024 ii. Date first reported: 11-05-2024
iii. Date of first investigation: 12-05-2024
iv. Date of follow-up investigation:
v. Time investigation started:
vi. Estimated quantity spilled: N/A

4. Site Details

- i. Site/Location: 8" O&G - INDORAMA ELEME (NGL) PIPELINE AT OMERELI COMMUNITY
ii. Position of Spill/Leak: NOS 13' 12.7" E006° 50' 01.7"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) NON-GAS LEAK

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) SABOTAGE

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify) 2" BALL VALVE WITH 2" PIPE CONNECTED ON THE PIPELINE AT 12 O' CLOCK POSITION BY UNKNOWN PERSON(S).

KP 256

2024/4/11/11/054

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.. N.O SAMPLES COLLECTED AT THE TIME OF J.W.

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation Repair was carried out immediately after J.W. exercise. Surveillance should be intensified on the company pipeline right at the end (Row).

12. Time Investigation ended.....

13. Name and Signature of Participants