

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... NONE

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation. ① Immediate clean-up of the affected area should be effected. ② Company should provide relief materials to community. ③ The portion of the pipeline affected should be repaired immediately. ④ Company should carry out damage assessment.

12. Time Investigation ended..... 1400 HRS