



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company

SEPLAT ENERGY

2. Type of Complaint/Incident

☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify) ASSET DAMAGE

3. Incident Details

- i. Date of Incident 18 / 09 / 24 ii. Date first reported 18 / 09 / 24
iii. Date of first investigation 21 / 09 / 24 iv. Spill Incident No. SEPLAT/HA/OS/23/2024
v. Date of follow-up investigation:
vi. Time investigation started: 12:23 PM
vii. Estimated quantity spilled(bbls): N/A viii. Quantity Recovered: A/A

4. Site Details

- i. Site/Location: 10th OBEH-AMUKPE DELIVERY LINE R/W
ii. State: DELTA iii. L.G.A: EFFIOPE WEST
iv. Spill Co-Ordinates: N(m): 05° 56' 54.2"
E(m): 0° 50' 48" 06.0"

v. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☒ Others (specify) NONE

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock ☐ 9 O' Clock

ii. Type of Oil contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☒ Others (specify) N/A

iii. Facility

- ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Bop
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)

v. Visible Sign of Third Party Interference

- ☐ Hackers Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) 4th ball Valve illegally attached to
10th Oben - Amukpe Delivery Line R/W



6. Impact of Incident

i. Properties impacted by the incident

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water

☐ Movable objects ☒ Others (specify) NONE

ii. Nature of impact

☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☐ Withering of vegetation ☒ Others N/A

iii. Delineation of impacted area

☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

N/A

7. Type of properties/ structures if any, found outside the right-of-way

☐ Crops ☐ Fish farm/ Pond ☐ Fishing Net ☐ Manufacture

☐ Permanent ☒ Other: N/A

8. Extent of Impact

a) Community (indicate name)

i. Eyborogbo rd

ii.

iii.

iv.

b) Land (indicate area in m²)

i.

ii.

iii.

iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>/</u>	<u>/</u>	<u>/</u>

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>/</u>	<u>/</u>	<u>/</u>

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>/</u>	<u>/</u>	<u>/</u>

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
	<u>/</u>	<u>/</u>	<u>/</u>

10 Samples taken

N04E

11 Investigation carried out by

☒ Foot

☐ Boat

☐ Aircraft

12 Remarks/Recommendation

1. Repair damaged pipeline.
2. Intensify surveillance around the area.

13 Time investigation ended

3.00 pm

14 Name and Signature of Participants