



Fig1 Incident Point



Fig 2 Impacted Area



Fig 3 During excavation/ Repair



Fig 4 After Repair



Fig 5 Materials used by the bunkers



Fig 6 flowed spill to another community