

2015/LAR/134/353

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NOC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 13-09-2015 ii. Date first reported: 13-09-2015
iii. Date of first investigation: 14-09-2015
iv. Date of follow-up investigation: N/A
v. Time investigation started: 14:55 HRS
vi. Estimated quantity spilled: 2 BBLs

4. Site Details

- i. Site/Location: Ebocha 4L FLL along old ebocha ferry road
ii. Position of Spill/Leak: N05°26'58.3 E006°40'50.1"
iii. Spill area: N05 26' 58.3 E006° 40' 50.3"

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock ☒ 10 0'Clock ☒ 2 0'Clock ☒ 3 0'Clock
☒ 4 0'Clock ☒ 5 0'Clock ☒ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify) The flowline was harvested in part about 10 metres.

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
- ☒ Fish Pond
- ☒ Vegetation
- ☒ Fishing Net
- ☒ Surface water
- ☒ Venerable Objects
- ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation
- ☒ Oil stained fishing nets
- ☒ Dead floating fishes
- ☒ Dead floating crabs
- ☒ Withering of vegetation
- ☒ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company’s facility/ROW
- ☐ Outside Company’s facility/ROW

7. Extent of Impact

- (a) Community (Indicate name)

i. Old Ebrima ferry road, Obarikam

ii.

iii.

iv.
- (b) Land (Indicate area in m²)

309.99m²

ii.

iii.

iv.

- (c) Creek/Creek lets
- ☒ Tidal
- ☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A	N/A	N/A	N/A

- (d) Swamp
- ☒ Tidal
- ☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A	N/A	N/A	N/A

- (e) River
- ☒ Tidal
- ☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A	N/A	N/A	N/A

- (f) Shoreline/water
- ☒ Tidal
- ☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A	N/A	N/A	N/A

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

Urgent clean-up of the impacted area should be carried out and surveillance of the facility should be improved.

12. Time Investigation ended.....

1515HRS