

 CamScanner

CS CamScanner

 CamScanner

☐ Hack saw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid

☒ Others (specify). *Attacker's dent of nose (pipes)*
on the wall head.

6. Impact of Incident

i Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....
 ii. Nature of impact
☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....
 iii. Delineation of impacted area
☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

- ☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... HONOLULU

10. Investigation carried out by

- ☐ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation. HONOLULU HAS MANY DRAFTS TO

REPAIR THE LOCAL HIGHWAYS

.....

12. Time investigation ended..... 14:06 hrs

13. Name and Signature of Participants