

19. Photographs:



Fig 1. Incident point during initial assessment




Fig 2. Incident point after repairs