

19. Photographs:



Fig 1. Incident point after exposing the pileline



Fig 2. Incident point after repairs