



National Oil Spill Detection and Response Agency

JOINT INVESTIGATION VISIT (JIV) FORM


Note: This JIV Form is to be completed by all participating parties in the field

Site Organization		Mandatory Information Required	
Company Name		NEPL	
Incident Number		2025/001	
Type of Complaint/Incident		☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution ☐ Others (specify).....	
Incident Details			
Date of Incident		13 04 2025	
Date first reported		14 04 2025	
Date of first investigation		15 04 2025	
Date of follow-up investigation		17 04 2025	
Time of investigation			
Estimated quantity spilled		20 BARRELS (RECOVERED 13.5 BARRELS)	
Site Details			
Facility Address		ELEKPO COMMUNITY	
Position of Spill/Leak			
Location	13	GPS Coordinate	N 4.513442 E 7.731680
Spill Area			
		☒ Land ☐ Swamp ☐ Fresh Water ☒ Mangrove ☐ Coastline ☐ Nearshore ☐ Offshore ☐ Others observations around the spill point (specify).....	
Structural Controls in Place		☐ Boom ☒ Trenches ☒ Bund wall ☐ Sorbents ☐ Others (specify).....	
Circumstances Around Spill point			
Visual Observation of Hole Point		☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock ☐ 4 O' Clock ☐ 5 O' Clock ☒ 6 O' Clock	
Type of Contaminant		☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products ☐ Others (specify).....	
Facility		☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....	
Cause of spill		Company	Third Party Interference
		☐ Corrosion ☒ Equipment Failure ☐ Operational/Maintenance Error ☐ Bund wall overflow	☐ Vandalization ☐ Oil Theft ☐ Illegal Refining ☐ Others
		Others ☐ Accident ☐ Mystery	

Additional Description of
Leak Point

- | | |
|--|---|
| ☐ Hack saw Marks | ☐ Drilled Holes |
| ☐ Hack saw cut | ☐ Blast |
| ☐ Theft (illegal bunkering) | ☐ Flare System/Blind well failure |
| ☐ Valve failure | ☐ Saver pit overflow |
| ☐ Missing Pipeline/Flowline | ☐ Third party tampering with valve setting |
| ☐ Failed Clamp | ☐ Third party tampering with flange |
| ☐ Well head tampering | ☐ Inward dent |
| ☐ Failed clamp | ☐ Surge vessel overflow |
| ☐ Bulging outward | ☐ Relief valve failure |
| ☐ Complete rupture | ☐ Others (specify) <i>Tamper, valve leak</i> |

Graphic Description of Leak Point (sketches/illustrations)



Project site information

Project site location: ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

Nature of impact

☐ Oil stained vegetation ☐ Oil stained fishing net ☐ Dead floating fishes
☐ Dead floating crab ☐ Withering of vegetation
☐ Others (specify).....

Distance from the nearest

Nearest protection of law

☐ Farmland [] m ☐ Build-up area [] m
☐ Fish Farm/ Pond [] m ☐ Drinking water source [] m
☐ Farmland/Fishing [] m ☐ Reserved and protected area [] m

Location of impacted area

☐ Within Company's facility ROW ☒ Outside Company's facility/ROW

Extent of impact

S/N	Nothing	Easting	S/N	Nothing	Easting
1	15 2 2 7	15 2 2 7			
2	15 2 2 7	15 2 2 7			
3	15 2 2 7	15 2 2 7			
4	15 2 2 7	15 2 2 7			
5	15 2 2 7	15 2 2 7			
6	15 2 2 7	15 2 2 7			
7	15 2 2 7	15 2 2 7			
8	15 2 2 7	15 2 2 7			
9	15 2 2 7	15 2 2 7			
10	15 2 2 7	15 2 2 7			
11	15 2 2 7	15 2 2 7			
12	15 2 2 7	15 2 2 7			
13	15 2 2 7	15 2 2 7			
14	15 2 2 7	15 2 2 7			
15	15 2 2 7	15 2 2 7			
16	15 2 2 7	15 2 2 7			
17	15 2 2 7	15 2 2 7			
18	15 2 2 7	15 2 2 7			
19	15 2 2 7	15 2 2 7			
20	15 2 2 7	15 2 2 7			

a) Community (indicate name)

i.

ii.

iii.

iv.

b) Land (indicate area in m²)

i. 93,521 m²

ii.

iii.

iv.

Creeks/ Creek lots

☐ Tidal ☐ Non Tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Swamp

☐ Tidal ☐ Non Tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

River

☐ Tidal ☐ Non Tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Shoreline/water			
☐ Tidal		☐ Non Tidal	
NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Photograph/Map/Chart Ref.	☒ Still Photograph	☒ Video coverage	☐ Mapping
Samples taken			
Investigation	☒ Foot	☐ Boat	☐ Aircraft ☐ Drone

REMARKS/RECOMMENDATION

The oil impacted area should be cleaned immediately
 by the company.
 The affected boat should be repaired immediately.
 The time should be spent in immediately.
 The community should be compensated based on the impacted area.

DATE/TIME INVESTIGATION ENDED 17/4/2025 12:18hrs.