



National Oil Spill Detection and Response Agency

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed by all participating parties in the field

Site Organization		Mandatory Information Required	
Company Name		SEPLAT ENERGY PRODUCTION NIGERIA UNLIMITED	
Incident Number		009/2025	
Type of Complaint/Incident		☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution ☐ Others (specify).....	
Incident Details			
Date of incident		30-06-2025	
Date first reported		30-06-2025	
Date of first investigation		04-07-2025	
Date of follow-up investigation		DD-MMM-YYYY	
Time of investigation		24h/13hrs	
Estimated quantity spilled		BARREL TBD	
Site Details			
Facility Address		SEPNY CRT	
Position of Spill/Leak		TANK 5003	
Location OML:		GPS Coordinate	N E
Spill Area		☐ Land ☐ Swamp ☐ Fresh Water ☐ Mangrove ☐ Coastline ☐ Nearshore ☐ Offshore ☒ Others observations around the spill point (specify)..... <u>within bund wall</u>	
Structural Controls in Place		☐ Boom ☐ Trenches ☒ Bund wall ☐ Sorbents ☐ Others (specify).....	
Circumstances Around Spill point			
Visual Observation of Hole Point		☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock ☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock	
Type of Contaminant		☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products ☐ Others (specify).....	
Facility		☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig ☒ Storage Tank ☐ Compressor Plant ☐ Others (specify).....	
Cause of spill		Company	Third Party Interference
		☐ Corrosion ☒ Equipment Failure ☐ Operational/Maintenance Error ☐ Bund wall overflow	☐ Vandalization ☐ Oil Theft ☐ Illegal Refining ☐ Others
		☐ Accident ☐ Mystery	

Description of Caul Piles	Description of	
	1	2
	☐ Moderate decay	☐ Severe decay
	☐ Moderate rot	☐ Rot
	☐ Thick (deep) burrowing	☐ Flare System, Band wall failure
	☐ Vague failure	☐ Severe rot surface
	☐ Missing Pipeline/Flowline	☐ First party sampling with note setting
	☐ Failed Clamps	☐ First party sampling with flange
	☐ Well head compaction	☐ Inward dent
	☐ Failed clamps	☐ Large metal surface
	☐ Missing out-cast	☐ Failed metal failure
	☐ Complete rupture	☐ Other (specify)

Graphic Description of Causal Piles (see top, bottom)

Take roof down was accompanied with cracks in a number of the heavy walls.

Upon inspection during the storm led to the removal of the split cracks within the basement.

Cracks is half measured for the basement at the base of the

Properties impacted by incident	☒ Farmland ☐ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
Nature of impact	☒ Venerable Objects ☒ Others (specify).... <u>ML</u>

☒ Oil stained vegetation : ☒ Oil stained fishing net ☒ Dead floating fishes
☒ Dead floating Crabs ☒ Withering of vegetation
☒ Others (specify) Oil in water on bund wall

☐ Farmlands [,m]	☒ Build-up area 2 [K,m]
☐ Fish Farm/Pond [,m]	☐ Drinking water source [,m]
☐ Farms ☐ Fishing [,m]	☐ Reserved and protected area [,m]

☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW[illegible]

- i. Q.T. = TAXE PAID
- ii. ~~_____~~
- iii. _____
- iv. _____

i. _____
ii. _____
iii. _____
iv. _____

☐ Tidal		☐ Non Tidal	
NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

☐ Tidal		☐ Non Tidal	
NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

☐ Tidal		☐ Non Tidal	
NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Shoreline/Water

☐ Tidal

NAME

DIRECTION OF SLICK

Length of Slick

Width of Slick

Width of Slick

N/A

Photograph/Map/Chart Ref.

☒ Still Photograph

☐ Video coverage

☐ Mapping

Samples taken

NIL

Investigation

☐ Foot

☐ Boat

☒ Aircraft

☐ Drones

REMARKS/RECOMMENDATION

Ensure continuing presence of bodies in water within the landward and seaward limits of the investigation. Commence clean up of affected landward areas.

DATE/TIME INVESTIGATION ENDED

04-07-2025 / 15:00 hrs

Name and Signature of Participants

NOSDRA

Local Government Council

S/N

Name

Signature

S/N

Name

Signature

1.

Odunlade, A. E

[Signature]

1.

2.

21126-1077

[Signature]

2.