



National Oil Spill Detection and Response Agency
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed by all participating parties in the field

Site Organization		Mandatory Information Required	
Company Name		SEPLAT ENERGY PRODUCING INC. UNLIMITED	
Incident Number		010/2025	
Type of Complaint/Incident		☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution ☐ Others (specify).....	
Incident Details			
Date of Incident		DD: MM: YYYY 07-07-2025	
Date first reported		DD: MM: YYYY 01-07-2025	
Date of first investigation		DD: MM: YYYY 04-07-2025	
Date of follow-up investigation		DD: MM: YYYY —	
Time of investigation		24hrs 13:00 hrs	
Estimated quantity spilled		BARRELS TRD	
Site Details			
Facility Address		SEPNU EIT	
Position of Spill/Leak		TANIK 5005	
Location		GPS Coordinate	N: DD: MM: SS E: DD: MM: SS
Spill Area			
		☒ Land ☒ Swamp ☒ Fresh Water ☒ Mangrove ☒ Coastline ☒ Nearshore ☐ Offshore ☒ Others observations around the spill point (specify)..... within bund wall.....	
Structural Controls in Place		☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....	
Circumstances Around Spill point			
Visual Observation of Hole Point		☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock ☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock	
Type of Contaminant		☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products ☒ Others (specify).....	
Facility		☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig ☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....	
Cause of spill		Company	Third Party Interference
		☒ Corrosion ☒ Equipment Failure ☒ Operational/Maintenance Error ☒ Bund wall overflow	☒ Vandalization ☒ Oil Theft ☒ Illegal Refining ☒ Others
		☒ Accident ☒ Mystery	

Additional Description of
Spill Point

- ☐ Hacksaw Marks
- ☐ Hacksaw cut
- ☐ Theft (illegal bunkering)
- ☐ Valve failure
- ☐ Missing Pipeline/Flowline
- ☐ Failed Clamp
- ☐ Well head tampering
- ☐ Failed clamp
- ☐ Bulging outward
- ☐ Complete rupture

- ☐ Drilled Holes
- ☐ Blast
- ☐ Flare System/Bund wall failure
- ☐ Saver pit overflow
- ☐ Third party tampering with valve setting
- ☐ Third party tampering with flange
- ☐ Inward dent
- ☐ Surge vessel overflow
- ☐ Relief valve failure
- ☐ Others (specify).....

Graphic Description of Leak Point (sketches/illustrations)

Roof drains minimal quantity of crude into the bundwall.
Crude contained in bundwall and recovery is in progress.

Impact of Incident

Properties impacted by incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify) *Tank Bund wall*

Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing net ☒ Dead floating fishes
☒ Dead floating Crabs ☒ Withering of vegetation
☒ Others (specify).....

Distance from the nearest Receptors potentially at risk

- ☐ Farmlands [,m] ☐ Build-up area *2 [k.m]*
☐ Fish Farm/Pond [,m] ☐ Drinking water source [,m]
☐ Farms ☐ Fishing [,m] ☐ Reserved and protected area [,m]

Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

Extend of Impact

S/N	Northing	Easting	S/N	Northing	Easting
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS
	: DD : MM : SS	: DD : MM : SS		: DD : MM : SS	: DD : MM : SS

a) Community (indicate name)

- i. *Q.I.L. Tame Farm*
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

Creeks/Creek lets

☐ Tidal

☐ Non Tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Swamp

☐ Tidal

☐ Non Tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

River

☐ Tidal

☐ Non Tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Shoreline/water			
☐ Tidal			
☐ Non Tidal			
NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
N/A			

Photograph/Map/Chart Ref.	☒ Still Photograph ☒ Video coverage ☒ Mapping
Samples taken	NIL
Investigation	☒ Foot ☒ Boat ☒ Aircraft ☐ Drone

REMARKS/RECOMMENDATION

Recover spill crude noticed within bundwall and
 Commence clean-up of the impacted bundwall.

DATE/TIME INVESTIGATION ENDED 24-07-2025 / 15:00hrs

Name and Signature of Participants					
NOSDRA			Local Government Council		
S/N	Name	Signature	S/N	Name	Signature
1.	Odunade, A.E.	[Signature]	1.		