



Fig A: Spill point just before excavation



Fig B: Pegging of the spill point



Fig C: Wrapping/Tape coating of incident facility



Fig E: Backfill after repair of incident facility



SPILL POINT