

PICTURES ON SITE:



 **Figure 1: BEFORE EXCAVATION**




Figure 2: BLAST POINT FOUND AFTER EXCAVATION



FIGURE: 3 REPAIR WORK