

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation

The clean-up of the impacted area should be carried out as soon as possible. The NMPC Ltd should intensify its security architecture on the facility.

12. Time Investigation ended

15:06 HRS.