



National Oil Spill Detection and Response Agency
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed by all participating parties in the field


Site Organization		Mandatory Information Required	
Company Name		TULCAN ENERGY	
Incident Number		TUL/TSB/INC001/2026	
Type of Complaint/Incident		☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution ☐ Others (specify).....	
Incident Details			
Date of Incident		01/04/2026	
Date first reported		02/04/2026	
Date of first investigation		06/04/2026	
Date of follow-up investigation			
Time of investigation		1100HRS - 1300HRS	
Estimated quantity spilled		NOT YET DETERMINED	
Site Details			
Facility Address		1.5KM FROM TULCAN ENERGY LAST UNIT LOCATION	
Position of Spill/Leak			
Location OML:	PPL-244 Tem-Sofot Bank PIPELINE ROW	GPS Coordinate	N 504233 E 410732
Spill Area		☒ Land ☒ Swamp ☐ Fresh Water ☐ Mangrove ☐ Coastline ☐ Nearshore ☐ Offshore ☐ Others observations around the spill point (specify).....	
Structural Controls in Place		☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☐ Others (specify).....	
Circumstances Around Spill point			
Visual Observation of Hole Point		☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock	
Type of Contaminant		☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products ☐ Others (specify).....	
Facility		☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....	
Cause of spill	Company	Third Party Interference	Others
	☐ Corrosion ☐ Equipment Failure ☐ Operational/Maintenance Error ☐ Bund wall overflow	☒ Vandalization ☐ Oil Theft ☐ Illegal Refining ☒ Others	☐ Accident ☐ Mystery

Additional Description of Spill Point

- ☐ Hacksaw Marks
- ☐ Hacksaw cut
- ☐ Theft (illegal bunkering)
- ☐ Valve failure
- ☐ Missing Pipeline/Flowline
- ☐ Failed Clamp
- ☐ Well head tampering
- ☐ Failed clamp
- ☐ Bulging outward
- ☐ Complete rupture

- ☒ Drilled Holes
- ☐ Blast
- ☐ Flare System/Bund wall failure
- ☐ Saver pit overflow
- ☐ Third party tampering with valve setting
- ☐ Third party tampering with flange
- ☐ Inward dent
- ☐ Surge vessel overflow
- ☐ Relief valve failure
- ☐ Others (specify).....

Graphic Description of Leak Point (sketches/illustrations)



An unknown person tampered with the Pipeline.
At the time of excavation a clothes was observed wrapped around the pipeline.

Impact of Incident

Properties Impacted by incident ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

Nature of impact ☒ Oil stained vegetation ☐ Oil stained fishing net ☐ Dead floating fishes
☐ Dead floating Crabs ☐ Withering of vegetation
☐ Others (specify).....

Distance from the nearest Receptors potentially at risk ☐ Farmlands [,m] ☐ Build-up area [,m]
☐ Fish Farm/Pond [,m] ☐ Drinking water source [,m]
☐ Farms ☐ Fishing [,m] ☒ Reserved and protected area [,m]

Delineation of impacted area ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

Extend of Impact					
S/N	Northing	Easting	S/N	Northing	Easting
1	504262	410718		DD : MM : SS	DD : MM : SS
2	504233	410732 (LP)		DD : MM : SS	DD : MM : SS
	DD : MM : SS	DD : MM : SS		DD : MM : SS	DD : MM : SS
	DD : MM : SS	DD : MM : SS		DD : MM : SS	DD : MM : SS
	DD : MM : SS	DD : MM : SS		DD : MM : SS	DD : MM : SS
	DD : MM : SS	DD : MM : SS		DD : MM : SS	DD : MM : SS
	DD : MM : SS	DD : MM : SS		DD : MM : SS	DD : MM : SS
	DD : MM : SS	DD : MM : SS		DD : MM : SS	DD : MM : SS
	DD : MM : SS	DD : MM : SS		DD : MM : SS	DD : MM : SS
	DD : MM : SS	DD : MM : SS		DD : MM : SS	DD : MM : SS
	DD : MM : SS	DD : MM : SS		DD : MM : SS	DD : MM : SS
	DD : MM : SS	DD : MM : SS		DD : MM : SS	DD : MM : SS
	DD : MM : SS	DD : MM : SS		DD : MM : SS	DD : MM : SS
	DD : MM : SS	DD : MM : SS		DD : MM : SS	DD : MM : SS

a) Community (indicate name)	b) Land (indicate area in m ²)
i.	i.
ii.	ii.
iii.	iii.
iv.	iv.

Creeks/Creek lets

☐ Tidal ☐ Non Tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Swamp

☐ Tidal ☐ Non Tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

River

☐ Tidal ☐ Non Tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

Shoreline/water			
☐ Tidal		☐ Non Tidal	
NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
/	/	/	/

Photograph/Map/Chart Ref.	☒ Still Photograph ☒ Video coverage ☐ Mapping
Samples taken	NIL
Investigation	☒ Foot ☐ Boat ☐ Aircraft ☐ Drone

REMARKS/RECOMMENDATION

Commence recovery immediately and
 carry out clean-up of all impacted area.
 Ensure surveillance of the pipeline ROW.

DATE/TIME INVESTIGATION ENDED.....

Name and Signature of Participants					
NOSDRA			Local Government Council		
S/N	Name	Signature	S/N	Name	Signature