

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIA AGIP OIL COMPANY
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
 - ☒ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 10/02/16 ii. Date first reported: 10/02/2016
 - iii. Date of first investigation: 10/02/16 iv. Spill Incidence No: 2016/SAR/036
 - v. Date of follow-up investigation: 15/02/2016
 - vi. Time investigation started: 2:30 PM
 - vii. Estimated quantity spilled(bbls): 180 bbls viii. Quantity Recovered:.....
4. Site Details
 - i. Site/Location: 14" OGBODINBIRI/TEBIDABA PIPELINE @ IKSINGHABIRI
 - ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAW LOCAL GOV. AREA
 - iv. Spill Co-ordinates: N(m) 04° 42' 20.41"
E(m) 005° 58' 06.74"
 - v. Spill area
 - ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
 - ☒ Near shore ☒ Offshore ☒ Others (specify).....
 - vi. Structural Controls in Place
 - ☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
 - ☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
 - ☒ Others (specify).....
 - iii. Facility
 - ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
 - ☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
 - iv. Cause Of Spill.
 - ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
 - ☒ Operational Error ☒ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
 - ☒ Others (specify)..... N/A

- i. **Properties impacted by the incident**
☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify).....

ii. **Nature of impact**

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....

iii. **Delineation of impacted area**

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. **Type of properties/ structures, if any, found outside the right-of-way**

- ☒ Crops ☒ Fish Farm/ Pond ☒ Fishing net ☒ Makeshift
☒ Permanent ☒ Others *N/A*

8. **Extent of Impact**

a) **Community (indicate name)**

i. IKENGHEN BIRI

ii.

iii.

iv.

b) **Land (indicate area in m²)**

i.

ii.

iii.

iv.

b) **Creeks/Creek lets**

☒ Tidal

☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) **Swamp**

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) **River**

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) **Shoreline/water**

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.
☒ Still photographs ☒ Video coverage ☒ Mapping
10. Samples taken..... N/A
11. Investigation carried out by
☒ Foot ☒ Boat ☒ Aircraft
12. Remarks/Recommendation LEAK WAS FROM PREVIOUSLY REPAIR
POINT. FAILURE OF PREVIOUSLY INSTALLED CLAMP.
JIV/REPAIR WAS CARRIED OUT. IMPACTED AREA SHOULD BE
CLEANED.
13. Time investigation ended 6:30 PM
14. Name