

EVIDENCE OF PHOTOGRAPH TAKEN AT SITE



Figure 2.1. Spill point



Figure 2.2. Failed orifice (Seal)