

3. EVIDENCE OF PHOTOGRAPH TAKEN AT SITE



Figure 2.1.

Incident (Blast) Point



Figure 2.2.

Complete welded section



Figure 2.3. Rapped point



Figure 2.4 Recovered Items from site.



Figure 2.5

Burnt Excavator.