

PHOTOGRAPHS ON SITE



INCIDENT POINT



AFTER EXCAVATION



AFTER REPAIRS



OIL SPILLED WITH ROW AND VEGETATION



VOLUME OF GAS TESTED DURING THE JIV