

JIV was not necessary and repairs was carried out
PHOTOGRAPHS ON SITE



INCIDENT POINT



AFTER EXCAVATION



AFTER REPAIRS



VOLUME OF GAS TESTED DURING THE JIV