



22

566

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIA AGIP OIL COMPANY
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 22.03.2016 ii. Date first reported: 22.03.2016
iii. Date of first investigation: 22.03.2016 iv. Spill Incidence No.: 2016/SAR/056
v. Date of follow-up investigation: -/-/-
vi. Time investigation started: 11:58 HRS
vii. Estimated quantity spilled(bbls): 3 BBLs viii. Quantity Recovered:.....
4. Site Details
i. Site/Location: 18" TEBI DABA / BRASS PIPELINE AT BENIKRUKRI
ii. State: BAYELSA iii. L.G.A.: SOUTHERN ITAW
iv. Spill Co-ordinates: N(m) N04° 32' 13.6"
E(m) E005° 58' 47.0"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
vi. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify)..... N/A
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify).....
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
iv. Cause Of Spill.
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify).....

- 23 567
- i. Properties impacted by the incident
 - ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
 - ☐ Venerable Objects ☐ Others (specify).....
 - ii. Nature of impact
 - ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
 - ☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....
 - iii. Delineation of impacted area
 - ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW
7. Type of properties/ structures, if any, found outside the right-of-way
- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
 - ☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. BENIKRUKRU
- ii.
- iii.
- iv.

b) Land (indicate area in m²)

- i. 3,953 m²
- ii.
- iii.
- iv.

b) Creeks/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

12. Remarks/Recommendation. UNKNOWN PERSON(S) INSTALLED 3" VALVE ON THE FACILITY FOR OIL THEFT ACTIVITIES. INCREASE SURVEILLANCE ~~FOR~~ TO AVOID FUTURE INCIDENT

13. Time investigation ended 15:50 HRS

24

568

9