

hours to the time of the first JRV but there was still pressure in the pipeline).
PICTURE TAKEN AT SITE



Figure 2.1. 250mm long hacksaw cut with dent



Figure 2.3. Leak Point patch welded