

### 3. PICTURES TAKEN AT SITE



**Figure 2.1**

**Bunkering Point**



**Figure 2.2.**

**Leak Point patch welded**