



After excavation.



Patch welded.



Repaired.