

PHOTOGRAPHS TAKEN ON SITE




Fig 1: Impacted area



Fig 2: Spill point



Fig 3: Leak point after repairs



Fig 4: Repaired point wrapped