



200mm Hacksaw cut on the facility at Point A (Before repair)



Hacksaw cut on the Facility at Point A (After repair)



A Section of the Facility, Point B on which Explosive device was used by the Suspect (Before repair)



Picture of the Point B on the Facility (After repair)



Picture of the Impacted Area (Within the Company's right of way)