

**PHOTOGRAPHS TAKEN ON SITE: 10' CLOUGH CREEK/TEBIDABA PIPELINE AT AZAGBENE**



**A: SITE PONT ARRIVAL**



**B: LEAK POINT AFTER OPENING AND PEGGING**



**C: PATCH PLATING OF LEAK POINT**



**D: WRAPPING OF REPAIRED POINT**