



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
 - Oil Pollution Fire/Explosion Drilling Mud/Chemical Pollution
 - Others (Specify).....
3. Incident Details
 - i. Date of Incident: 14/01/2017 ii. Date first reported: 14/01/2017
 - iii. Date of first investigation: 14/01/2017 iv. Spill Incidence No. 2017/SAR/002
 - v. Date of follow-up investigation:...../...../.....
 - vi. Time investigation started: 12:10 PM
 - vii. Estimated quantity spilled(bbls): 0.05 BBL viii. Quantity Recovered: MOPPED UP
4. Site Details
 - i. Site/Location: 18" TEBIDABA/BRASS PIPELINE AT BENIKRUKRU
 - ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAW
 - iv. Spill Co-ordinates: N(m) 04° 32' 13.9"
E(m) 005° 58' 45.4"
 - v. Spill area
 - Land Swamp Freshwater Mangrove Coastline
 - Near shore Offshore Others (specify).....
 - vi. Structural Controls in Place
 - Boom Trenches Bund wall Sorbents Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - 12 O' Clock 10 O' Clock 2 O' Clock 3 O' Clock
 - 4 O' Clock 5 O' Clock 6 O' Clock
 - ii. Type of Oil contaminant
 - Crude Oil Condensate Chemicals Refined Products
 - Others (specify).....
 - iii. Facility
 - Pipeline Flow line Wellhead Manifold Flow Station Rig
 - Storage Tank Compressor Plant Others (specify).....
 - iv. Cause Of Spill
 - Corrosion Equipment Failure Third Party Interference Accident
 - Operational Error Others (specify).....
 - v. Visible Sign of Third Party Interference
 - Hacksaw Marks Drilled Holes Blasting Theft Acid
 - Others (specify) 3" VALVE WITH 2" PIPE CONNECTION ATTACHED TO THE FACILITY.



6. Impact of Incident

i. Properties Impacted by the incident

- Farmland Fish Pond Vegetation Fishing Net Surface water
 Venerable Objects Others (Specify) *MAINLY SWAMP*

ii. Nature of impact

- Oil stained vegetation Oil stained fishing nets Dead floating fishes
 Dead floating crabs Withering of vegetation Others (Specify) *nil*

iii. Delineation of Impacted area

- Within Company's facility/ROW Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

8.14 m²

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets Tidal Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp Tidal Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River Tidal Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water Tidal Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

Still photographs Video coverage Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

Foot Boat Aircraft

11. Remarks/Recommendation..... *NAOC SHOULD INTENSIFY SECURITY ALONG ITS PIPELINES TO REDUCE SABOTAGE INCIDENTS.*

12. Time Investigation ended..... *1:56 PM*