

PICTURE TAKEN AT SITE



Figure 2.1. The Incident Point




Figure 2.2. Oil sheen on water

