

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT (JIV)



Fig A: The Incident Area just before excavation



Fig B: Incident facility after excavation/Spilled Crude Oil