

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT (JIV)



Fig A: The Incident Facility/Leak Point




Fig B: Oil sheen within the Platform Area