

8. Photograph/Map/Chart Ref.

☒ Still photographs   ☐ Video coverage   ☐ Mapping

9. Samples taken..... *N/A* .....

10. Investigation carried out by

☒ Foot   ☐ Boat   ☐ Aircraft

11. Remarks/Recommendation.....

*The affected pipe has been  
pegged & clamped. The site appears clean  
and still under observation.*

12. Time investigation ended..... *1430 hrs* .....