



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC INCIDENT NO: 2017.1949075

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify) CLAMP THEFT

3. Incident Details

i. Date of Incident: 16-10-2017 ii. Date first reported: 16-10-2017

iii. Date of first investigation: 17-10-2017

iv. Date of follow-up investigation:

v. Time investigation started: 13.48 HOURS

vi. Estimated quantity spilled: NIL (NON-LEAKING POINT)

4. Site Details

i. Site/Location: 28" NKPOKU-BOMU PIPELINE @
NORKPO-TAIL LGA, RIVERS STATE.

ii. Position of Spill/Leak: N 04° 44' 09.24"

iii. Spill area: E 007° 12' 17.244"

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock
☒ 4 O'Clock ☒ 5 O'Clock ☒ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify) MISSING CLAMP REMOVED BY

v. Visible Sign of Third Party Interference

- ☒ Hack Saw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify) UNKNOWN PERSON(S)
A 28" X 1/4" PLIDCO SPLIT SLEEVE (HALF)
CLAMP PREVIOUSLY INSTALLED BY
SPDC ASSET OWNER WAS STOLEN.

6. Impact of Incident

i. Properties Impacted by the Incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify)

ii. Nature of Impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i. i.
 ii. ii.
 iii. iii.
 iv. iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken NON

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation 1. CLAMP SHOULD BE RE-INSTALLED.
2. THE AGENCY SHOULD BE NOTIFIED WHEN THAT
WILL BE DONE, TO MONITOR THE PROCESS.

12. Time Investigation ended 15.45 HOURS.

13. Name and Signature of Participants

- ◆ **NOSDRA**
1. KOMS ABAM [Signature] 17/10/2017
2. _____
3. _____
- ◆ **DPR**
1. _____
2. _____
3. _____
- ◆ **STATE MINISTRY OF ENVIRONMENT**
1. ORDY JAMES (Ramen) [Signature] 17/10/17
2. _____
3. _____
- ◆ **LOCAL GOVERNMENT COUNCIL**
1. _____
2. _____
3. _____
- ◆ **COMPANY**
1. CHINKEU ENACHUKWU [Signature] 17/10/17
2. MOMOH, IBRAHIM A. [Signature] 17/10/17
3. _____
- ◆ **COMMUNITY**
1. EMMANUEL NNEKORDE [Signature] 17/10/2017
2. _____
3. _____