

2017-1987291



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. **Company:** SPDC
2. **Type of Complaint/Incident:**
 - ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify).....
3. **Incident Details**
 - i. Date of Incident: 18/12/17 ii. Date first reported:.....
 - iii. Date of first investigation: 19/12/17
 - iv. Date of follow-up investigation: N/A
 - v. Time investigation started: 14.20 HRS
 - vi. Estimated quantity spilled: 10 BBL'S
4. **Site Details**
 - i. Site/Location: 28" BOMU - BOMBY INP @ PATRICK WATERSIDE
 - ii. Position of Spill/Leak:.....
 - iii. **Spill area**
 - ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify).....
 - iv. **Structural Controls in Place**
 - ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☒ Others (specify) N/A
5. **Circumstances Around Spill Point**
 - i. **Visual observation of Hole Position**
 - ☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. **Type of Oil contaminant**
 - ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
 - ☐ Others (specify)
 - iii. **Facility**
 - ☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
 - iv. **Cause Of Spill**
 - ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
 - ☐ Operational Error ☐ Others (specify).....
 - v. **Visible Sign of Third Party Interference**
 - ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
 - ☒ Others (specify) INSTALLED 6" OIL THEFT VALVE

6. Impact of Incident

i Properties impacted by the incident

☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (specify) LOW MANGROVE

ii. Nature of impact

☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others MANGROVE

iii. Delineation of impacted area

☐ Within Company's facility/ROW
 ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

i. BARRICK WATER SITE
 ii. _____
 iii. _____
 iv. _____

b) Land (indicate area in m²)

i. 24.00m
 ii. _____
 iii. _____
 iv. _____

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
//	/	//	//

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
//	//	//	//

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
//	//	//	//

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
//	//	//	//

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....N/A.....

10. Investigation carried out by

☐ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation...SPILL OCCURRED DUE TO INSTALLED
6" INLETH BUNKERING VALVE FOR OIL STEEL
ACTIVITIES.....

12. Time investigation ended.....1537 HRS.....

13. Name and Signature of Investigator.....