



nigerian agip oil company limited

Incorporated in Nigeria – RC 2974

Head Office: No. 40/42 Aguiyi Ironsi Street,
Maitama, Federal Capital Territory, Abuja, Nigeria.
Mail: P.M.B. 514, Abuja, Nigeria.
Telephone: +234 (0)9 4611900 – 6
Fax: +234 (0)9 4611911

District: Mile 4, Ikwerre Road, Port Harcourt, Nigeria.
Mail: P.O. Box 923, Port Harcourt, Nigeria.
Telephone: +234 (0)84 465010 – 9

Lagos: No. 1 Elsie Femi Pearse Street,
Victoria Island, Lagos, Nigeria.
Mail: P. O. Box 1268, Lagos, Nigeria.
Telephone: +234 (0)1 4628907 – 11

AOO/HSE/PH/5658/14

22nd September, 2014

The Zonal Director,
National Oil Spill Detection and Response Agency,
No. 32 Bodo Street,
GRA Phase II,
Port Harcourt.

Dear Sir,

OIL SPILL INSPECTION

Please, be informed that this letter is in reference to the oil spill incident that occurred along our 18" Tebidaba/Brass pipeline at Oyeregbene on 19/09/14 (Spill ref. no. 2014/SAR/515/708) for which the joint investigation visit was carried out on 19/09/14.

Yours faithfully,

Ayo Lateef
Health, Safety & Environment Manager

B
EST II (Madr H.)
Pls attend 13/10/14

R. Casula (Italian) - Chairman
M. Insulla (Italian) - Vice Chairman/Managing Director
O. Goka - Deputy Managing Director

G. Cerrito (Italian) - Director
C. N. Illoh - Director
E. Ebohon - Company Secretary

2014/SAR/SIS



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NATOC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 19/09/2014 ii. Date first reported: 19/09/2014
iii. Date of first investigation: 19/09/2014
iv. Date of follow-up investigation:
v. Time investigation started: 0812hrs
vi. Estimated quantity spilled: 5 litres

4. Site Details

- i. Site/Location: 18° TEBIDABA / BRASS BLK @ OYEREGBENE
ii. Position of Spill/Leak: N 04° 30' 25.6" E, 006° 02' 54.7"
iii. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☒ Others (Specify) nil

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☒ Others (Specify) unknown persons cut open the cone previously used as repairs on the pipe line.

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creeks

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.



Still photographs



Video coverage



Mapping

9. Samples taken.....

10. Investigation carried out by



Foot



Boat



Aircraft

11. Remarks/Recommendation.....

NOVOC STROUD WINTERFALL THER
SURVEILLANCE. REPAIRS CARRIED OUT ON 7TH
DAY.