



Fig B: Valve was cut and coned



Fig C: Wrapping/Tape coating of incident facility

