

Fig A: Spill point during excavation



Fig B: Wrapping/Tape coating of incident facility



Fig C: Backfill after repair of incident facility

