

PHOTOGRAPHS TAKEN DURING JIV



Fig A: Spill point just before excavation

Fig B: Spill point during excavation



Fig C: Pegging of the spill point



Fig D: Wrapping/Tape coating of incident facility

Fig E: Backfill after repair of incident facility

