



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NAOC
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 04/11/2015 ii. Date first reported: 04/11/2015
iii. Date of first investigation: 04/11/2015 iv. Spill Incidence No. 2015/SAR/262
v. Date of follow-up investigation: 04/11/2015
vi. Time investigation started: 10:11 HRS
vii. Estimated quantity spilled(bbls): 2 LITRES viii. Quantity Recovered: MOPPED UP
0.00063 Bbl BRASS
4. Site Details
i. Site/Location: 18" TEBIDABA PIPELINE AT OYEREGBEKE (36)
ii. State: BAYELSA iii. L.G.A: SILGA
iv. Spill Co-ordinates: N(m) N04° 30' 23.8"
E(m) E006° 03' 01.7"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
vi. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☒ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
- iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
- iv. Cause Of Spill.
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
- v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

- i. **Properties impacted by the incident**
☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....
- ii. **Nature of impact**
☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....
- iii. **Delineation of impacted area**
☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. **Type of properties/ structures, if any, found outside the right-of-way**
☒ Crops ☒ Fish Farm/ Pond ☒ Fishing net ☒ Makeshift
☒ Permanent ☒ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

h) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
///	///	///	///
///	///	///	///
///	///	///	///

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
///	///	///	///
///	///	///	///
///	///	///	///

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
///	///	///	///
///	///	///	///
///	///	///	///

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
///	///	///	///
///	///	///	///
///	///	///	///

9. Photograph/Map/Chart Ref.
☒ Still photographs ☐ Video coverage ☐ Mapping
10. Samples taken.....
11. Investigation carried out by
☐ Foot ☒ Boat ☐ Aircraft
12. Remarks/Recommendation..... UNKNOWN PERSON(S) CUT OFF 12" CONE
AND INSTALLED 4" VALVE FOR OIL THEFT ACTIVITIES. 14"
CONE WAS USED TO COVER THE POINT. SURVEILLANCE SHOULD INCREASE