


PICTURES TAKEN AT SITE:



SPILL POINT BEFORE EXCAVATION



BUNKERING POINT SHOWN



REPAIR WAS DONE BY CONNING.