

PHOTOGRAPHS TAKEN ON SITE



FIG 1-2: Excavated pit by vandals



FIG 3: JIV Team



Fig 4: Spill point (Hack saw cut)



5

FIG. 5: Oil recovery in progress



6

FIG 6: Repair work in progress



FIG 7: Clamp job completed