

PHOTOGRAPHS TAKEN ON SITE: 10' CLOUGH CREEK/TEBIDABA PIPELINE AT AZAGBENE



A: SITE PONT ARRIVAL



B: LEAK POINT AFTER OPENING AND PEGGING



C: CONING OF LEAK POINT



D: CRUDE RECOVERY ON SITE