

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT (JIV)



Fig A: Incident Facility (Agbaya Well 1 Wellhead)




Fig B: Position of stolen survey cap



Fig C: Oil Spill impacted area



Fig D: Containment boom(s) on SPDC's RoW.