



Picture showing pinhole on the wellhead.



Picture showing some of the impacted areas within the well slot.



Picture showing facility after repair.