

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT



Fig A: Incident Area on arrival of the JIT



Fig B: Adjoining environment/oil stained vegetation



Fig C: Incident Facility after excavation



Fig D: Incident facility during repair