

SOME PHOTOGRAPHS TAKEN DURING THE JOINT INVESTIGATION VISIT



Fig A: Incident Area on arrival of the JIT




Fig B: Incident Facility after excavation



Fig C: Incident facility shortly after repair



Fig D: Surrounding Environment/NAOC's RoW