

3. PICTURES TAKEN AT SITE:

SPILL POINT AFTER EXCAVATION: fig1



SPILL DURING REPAIR: fig2



SPILL POINT AFTER REPAIRS: fig3

