

5. PICTORAL EVIDENCE:



Spill point before excavation



Impacted vegetation



Affected section of facility